

UTAH STATE CAPITOL ARCHITECTURE: EXTERIOR SURVEY REPORT

ELEVATION LOCATION: WEST ELEVATION

Survey Date: 4/24/00

Code: EX-001

Description: Foundation stone

Location: base

Grid: B/S 74; B/N 30

Condition: J

Mortar joint with missing or loose mortar

Comments:



Code: EX-001

Description: Foundation stone


Location:

Grid: B/S 74

Condition: CR

Cracked element

Comments:



Code: EX-001

Description: Foundation stone

Location:

Grid: B/N 30

Condition: INT

Intrusive, non-original, non-essential element

Comments: plastic anchors, metal pipe, wire mesh over ventilation opening.



Code: EX-001

Description: Foundation stone

Location:


Grid: B/N 60


Condition: J

Mortar joint with missing or loose mortar

Comments: bricks exposed below EX-1.




Code: EX-001**Description:** Foundation stone**Location:****Grid:** B/ N 110**Condition:** BR, PATBroken element, poor quality
patching**Comments:****Code:** EX-001**Description:** Foundation stone**Location:****Grid:** B/N 110**Condition:** NONon-original, incompatible but
essential elements**Comments:** covered walkway, metal door--PH
25.**Code:** EX-001**Description:** Foundation stone**Location:** at front steps**Grid:** B/S 1**Condition:** BR, CR, INT, STBroken, cracked, stained element,
and intrusive element**Comments:** Int--plastic anchor; St--metal
protrusion; Rusting**Code:** EX-001**Description:** Foundation stone**Location:** arch underneath stairs, above gate**Grid:** B/S 1**Condition:** STSignificant Staining; may
indicate rusted connector**Comments:** efflorescence

Code: EX-002**Description:** Basement wall stone*Location:**Grid:**Condition:* J, STMortar joint damage and
significant staining*Comments:* around window**Code: EX-002****Description:** Basement wall stone*Location:**Grid:* B/S 35*Condition:* CR, J, STCracking, mortar joint damage,
and staining*Comments:* 2 alum vents--PH 28 W/ ST &
rough stone; NO ; plastic
anchors--PH 29/ NT**Code: EX-003****Description:** Lower belt course*Location:**Grid:**Condition:* STSignificant Staining; may
indicate rusted connector*Comments:* almost continuous**Code: EX-005****Description:** Pilaster base*Location:**Grid:* C/S 74*Condition:* NONon-original, incompatible but
essential elements*Comments:* metal restraint - bent, old holes,
metal remains

Code: EX-006**Description:** Pilaster shaft**Location:****Grid:** D/S 74**Condition:** CR, PATCracked element and poor quality
patching**Comments:****Code:** EX-008**Description:** Wall stone**Location:****Grid:****Condition:** PAT

Poor quality, non-matching patch

Comments: small**Code:** EX-009**Description:** Entablature lower belt**Location:****Grid:** F/N 110**Condition:** CR

Cracked element

Comments:**Code:** EX-009**Description:** Entablature lower belt**Location:****Grid:** F/N 30, F/S 30; F/S 70**Condition:** BRBroken, severely cracked or
chipped**Comments:**

Code: EX-010**Description:** Entablature frieze**Location:****Grid:****Condition:** STSignificant Staining; may
indicate rusted connector**Comments:** underneath, typ**Code:** EX-012**Description:** Entablature cornice**Location:****Grid:** G/N 80; G/N 69**Condition:** BRBroken, severely cracked or
chipped**Comments:** medallions**Code:** EX-012**Description:** Entablature cornice**Location:****Grid:** G/N 120**Condition:** BRBroken, severely cracked or
chipped**Comments:** cornice**Code:** EX-012**Description:** Entablature cornice**Location:****Grid:** G/S 25**Condition:** ST, CR

Significant staining and cracking

Comments: heavy rust colored stain

Code: EX-012**Description: Entablature cornice****Location:** at pediment**Grid:** H**Condition:** ST, CR

Significant staining and cracking

**Comments:** cracking, staining apparently from rusting flashing**Code: EX-014****Description: Pediment cornice****Location:****Grid:** G/S 70**Condition:** BR

Broken, severely cracked or chipped

**Comments:****Code: EX-017****Description: Balustrade baluster****Location:****Grid:** H/N 80**Condition:** EX

Exfoliated or spalled surface

**Comments:****Code: EX-017****Description: Balustrade baluster****Location:****Grid:** C/S 76**Condition:** CR

Cracked element

**Comments:**

Code: EX-067

Description: Window

Location: base

Grid: B/S 20

Condition: INT

Intrusive, non-original, non-essential element

Comments: metal anchors both sides



Code: EX-074

Description: Stairs

Location:

Grid: B/CL

Condition: BR

Broken, severely cracked or chipped

Comments:



Code: EX-078

Description: Light

Location:

Grid: C/S 6.6

Condition: GL

Glass cracked, broken or non-matching

Comments:



Code: EX-078

Description: Light


Location: at every window

Grid: C/N 110

Condition: NO

Non-original, incompatible but essential elements

Comments: spot lights



Code: EX-078

Description: Light

Location: entablature

Grid: G, K

Condition: NO

Non-original, incompatible but essential elements

Comments: square lights over round hole



Code: EX-093

Description: Trim

Location:

Grid: C/N 69

Condition: EX

Exfoliated or spalled surface

Comments:



Code: EX-094

Description: Trim

Location:

Grid: E/N 102

Condition: CR

Cracked element

Comments:



Code: EX-094

Description: Trim

Location:

Grid: E/N 102 & 90

Condition: BR

Broken, severely cracked or chipped

Comments:



Code: EX-094**Description:** Trim*Location:**Grid:***Condition:** PAT

Poor quality, non-matching patch

Comments: typical; small**Code:** EX-094**Description:** Trim*Location:**Grid:* F/E/N 74**Condition:** EX

Exfoliated or spalled surface

Comments: on S side of column**Code:** EX-102**Description:** Security Call box, megaphone*Location:**Grid:* C/CL**Condition:** NO

Non-original, incompatible but essential elements

Comments: security call box, megahose**Code:** EX-103**Description:** Window Sill*Location:**Grid:***Condition:** ST

Significant Staining; may indicate rusted connector

Comments: Window sill, 4th floor; TYP across West face, at sill edges, water draining insufficient.